

Failure Analysis and Field Repair of Urea reactor

Krishnan Sivaraman, Ravinder Singh, Abhishek Singh

Larsen & Toubro Limited, Heavy Engineering IC, Powai Campus, Mumbai, India

ABSTRACT

The outer shell of a Multi-layered Urea reactor ruptured while the plant was in operation. The plant made an emergency shutdown, samples were collected, and an investigation carried out to establish the root cause of the failure. The paper explains the detailed analysis performed, corrective action implemented, and a health assessment for the equipment's safe working. The paper also includes references to similar failures in old multi-layered urea reactors subsequently and the mitigation plans to avoid such failures.

Keywords: Case Study, Failure Analysis, Field Repair, Multi-layered Urea Reactor.

SAMRIDDHI: A Journal of Physical Sciences, Engineering and Technology (2022); DOI: 10.18090/samriddhi.v14i04.23

INTRODUCTION

The urea reactor is a critical component in any fertilizer plant. Urea is formed in the urea reactor by the ammonia and carbon dioxide reaction at elevated pressure and temperature. During normal operation of the urea plant, a sudden sound and a rupture were found in the outer shell layer of the urea reactor. Figure 1 shows the rupture of the outer shell, with a tearing of 1.5 m (4.9 ft) length. This multi-layer Urea reactor was supplied in 1982 and has been in operation for more than 35 years, with regular maintenance work carried out every 2 to 3 years, which included inner liner inspections and repairs.

This paper describes the investigation regarding physical and metallurgical findings for the multi-layered shell, detailed analysis, root cause of the failure, lessons learned, and the health assessment results. Furthermore, the paper covers an innovative approach implemented to perform an in-situ replacement of the defective liner segment during the emergency shutdown. Some modifications and the preventive actions implemented to avoid reoccurrence will also be discussed.

General Technical Data

Urea reactors are usually vertical pressure vessels, with either mono-wall, multi-layer, or multi-wall construction. Because



Figure 1: Tearing of urea reactor outer shell

Corresponding Author: Krishnan Sivaraman, Larsen & Toubro Limited, Heavy Engineering IC, Powai Campus, Mumbai, India, E-mail: Krishnan.Sivaraman@larsentoubro.com

How to cite this article: Sivaraman K, Singh R, Singh A. (2022). Failure Analysis and Field Repair of Urea reactor. *SAMRIDDHI: A Journal of Physical Sciences, Engineering and Technology*, 14(4), 143-149.

Source of support: Nil

Conflict of interest: None

of the corrosive nature of the medium, the interior surface of the vessel is lined with corrosion-resistant materials.

The design and construction features of the subject Urea reactor is shown in Table 1 and a diagram of features in a multi-layer urea reactor is shown in Figure 2.

Initial Inspection at Site

Visual inspection of the Urea reactor showed tearing of the outer shell layer resulting in a 1.5 m (4.9 ft) wide opening near the davit arm location, as shown in Figure 3a. Deflection of the davit arm and bulging near the ruptured zone were observed.

Heavy scale formation was observed on the outer shell as shown in Figure 3b. Thickness of the shell layer was reduced (~13.5 mm (0.53 in) against original 14.9 mm (0.59 in)), due to corrosion under insulation.

The fracture surface is shown in Figure 4, which shows pre-existing crack face and fresh rupture face. This pre-existing crack seems to have initiated near the edge of fillet weld between the manway davit arm pad plate and the outer shell layer.

The reduction in thickness of the outer shell layer near the ruptured zone was found to be ~2-3 mm (0.08-0.12 in).

Table 1: Design & Construction details

No.	Parameter	Value
1.	Construction	Multi-layered (7 layers)
2.	Total shell thickness	115.8 Mm
	Layers	No. & thickness Moc
3.	Inner liner	1 X 7 mm Sa240 tp 316lm
	Dummy layer	1 X 4.5 mm Jis ss41
	Outer layers	7 X 15 mm Sa 724 gr a
4.	Code of construction	Asme bpvc sec viii div-2, ed-1980
5.	Design pressure	169 Kgf/cm2(g)
6.	Design temperature	200°C
7.	Operating pressure	159 Kgf/cm2(g)
8.	Operating temperature	190°C (top) 170°C (bottom)




Figure 2: Constructional features of multi-layer




Figure 3: Tearing of outer shell and scale formation beneath insulation




Figure 4: Fracture surface on (a-b) Shell layer side (c) Davit arm pad side



Figure 5: Deposit collected from weep hole

No traces of carbamate/residue were observed in the ruptured portion of the shell/immediate inner shell surface in the vicinity of failure.

An air test was performed to find the leakage in the liner at the top portion of reactor (Top head + Shell). The test was not successful due to weep holes blockage. Further steam purging was carried out to clear the weep holes. Deposits were observed at the weep hole opening and collected for analysis (Figure 5).

Visual inspection and dye penetrant test (DPT) of the inside liner surface showed signs of corrosion on the longitudinal and circumferential weld joints, as shown in Figure 6. Corrosion was also observed on the weld built-up area buttering (old cleat removal area). Localized dents and bulges on liner surface were also observed.

After cutting and removal of the outer shell layer, the inside surface of the layer revealed discoloration towards weep hole-W9, as shown in Figure 7.

Air testing was conducted after the blockage in weep holes was removed. This revealed leakage in the liner long seam, in the area between the 1st and 2nd trays, as shown in Figure 8a. The leakage location was then verified by dye penetrant test (Figure 8b and 8c).

After cutting the liner plate at the leakage location, the inner dummy shell and 1st layer shell were corroded through as shown in Figure 9.

Investigation

To find out the cause of failure, a detailed investigation was carried out on extracted samples. The following tests were conducted:




Figure 6: Corrosion on liner Longitudinal seam (a-b) Circumferential seam (c-d)





Figure 7: Inside surface of outer shell layer




Figure 8: Leak found in air test and veri-fied in DPT

- Chemical Analysis
- Mechanical Testing
- Visual examination
- Macro examination
- Scanning electron microscopy (SEM) & Energy dispersive spectroscopy (EDS)
- Microscopic examination

Chemical Analysis

Chemical analysis by Optical emission spectroscopy was carried out to confirm the chemical composition of the shell layer. The results confirmed a match to the expected composition. These results are shown in Table 2.

Mechanical Testing

Tensile, impact, and hardness testing were carried out in the longitudinal and transverse directions. Tensile properties met the requirements of the material specification, as shown in Table 3.

Visual and Macro Examination

Samples collected from the failure location were thoroughly examined visually and using a stereoscope. The following observations were made:

The outside surface of the shell layer showed the presence of heavy scaling, as shown in Figure 10.

Table 2: Chemical composition of samples

Element (%)	Result	Requirement of SA 724 Gr-A
C	0.16	0.22 max
Si	0.39	0.60 max
Mn	1.38	0.92–1.72
P	0.013	0.025 max
S	0.006	0.025 max
Cr	0.025	0.29 max
Ni	0.003	0.28 max
Mo	0.002	0.090 max
Cu	0.007	0.38 max
V	0.043	0.090 max




Figure 9: Corrosion of dummy shell and 1st shell layer due to liner leakage

The inside surface shell layer revealed discoloration as shown in Figure 11. The residue was analyzed to be iron and oxygen.

A pre-existing crack (~3 mm (0.12 in) depth) was observed on the fracture face, and shown in Figures 12 and 13. This pre-existing crack appears to have initiated near the edge of the fillet weld between the manway davit arm bracket pad plate and the outer shell layer, as shown in Figure 14.

Table 3: Mechanical properties

Mechanical properties	Longitudinal direction	Transverse direction	SA 724 gr a®
Yield strength (mpa)	591	506	485 Min
U.T.S. (Mpa)	758	723	620-760
% Elongation	22.76	25.72	19 Min
Impact at 0°C (joules)	208,232,220	114.94.100
Hardness in (hbw)	215. 219.	219	****



Figure 10: Corrosion under insulation on outside surface



Figure 11: Brownish discoloration on inside surface




Figure 12: Failure location - Crack near fracture surface

Additionally, a small crack was observed near the fracture surface, which appeared to be generated due to mechanical force during fracture of shell layer (Figure 15).

After visual and macro examination of the extracted samples, specimens containing the failure locations were cut for subsequent analysis. Specimen containing the fillet weld (Pad plate to outer shell layer weld) showed a lack of fusion with shell layer (Figure 16).

SEM & EDS Analysis

SEM-EDS analysis was carried out on the specimens cut from extracted samples, scale formed on the outside surface of shell layer under insulation, and deposits collected from the weep hole.



Figure 13: Failure location - fracture surface pad plate side




Figure 14: Macro examination previously induced crack and fresh rupture – 10X




Figure 15: Crack beside fracture surface - 20X




Figure 16: Discontinuity in fillet weld between pad plate to shell layer - 20X

SEM of shell layer side part of the fracture surface clearly revealed a boundary between pre-existing crack and fresh rupture, as shown in Figure 17. The maximum depth of the crack was found to be ~3.7 mm (0.15 in).

A specimen containing the pad side part of the fracture surface that showed lack of fusion in the weld revealed a micro crack in the base metal adjacent to weld edge, as indicated in Figure 18. The edge of the weld was revealed,






Figure 17: SEM Image for boundary between previously induced crack and fresh rupture




Figure 18: SEM Image for crack on fracture face near weld




Figure 19: EDS on previously induced crack face

which appeared to be the initiation point of the pre-existing crack.

EDS revealed a significant amount of oxygen, iron, and other elements like sodium, calcium, and manganese on the pre-existing crack face and at the crack beside the fracture surface (Figures 19 and 20).

A significant presence of oxygen and iron, along with elements like sodium, manganese, calcium, and chlorine was observed on the crack face near the outside surface of shell layer. (Figure 21) A lower amount of oxygen was noticed on the rupture face as compared to the pre-existing crack face. This indicated low degree of oxidation on fresh rupture face.

Scale formed on the outer layer of the shell consisted mainly of iron and oxygen. (Figure 22)
The deposit collected from the weep hole showed significant presence of nitrogen, oxygen, and carbon (Figure 23).

Microscopic Examination

After SEM-EDS analysis; the cross-section surface of the specimen was polished and etched with 2% Nital and




Figure 20: EDS on crack beside fracture surface




Figure 21: EDS on rupture face




Figure 22: EDS of scale formed on shell layer

observed under a microscope. The following observations were made:

Microstructure of shell layer showed tempered martensitic structure (Figure 24).

The pre-existing crack appears to be initiated from edge of the fillet weld and propagated in heat affected zone (HAZ) in the outer shell layer. (Figure 25)

Secondary cracks beside the fracture surface were also observed (Figure 26)




Figure 23: EDS of deposit collected from weep hole




Figure 24: Microstructure near shell layer from outside - 50X




Figure 25: (a) Crack initiation point - 50X, (b-c) Crack propagating in HAZ - 50X and 100X




Figure 26: Crack beside fracture surface on shell layer - 50X and 100X

Weldability Test

Weldability of the shell layer material was verified by welding butt joint and clearing the dye penetrant test and radiography test.

SUMMARY OF OBSERVATIONS

- The chemical composition and mechanical properties of outer shell layer conforms to SA 724 Gr A, as per drawing

requirement. Microstructure of the material was found satisfactory. Weldability test carried out using shell layer material was also satisfactory. Based on this, it inferred that material had not degraded during service.

- During a visual inspection at site, heavy scaling due to corrosion was observed on the outside surface of the outer shell layer. Thickness of the shell was found to be reduced by 1.5 mm (0.06 in) due to scaling. EDS of the scale formed on the outer layer under insulation was found to be mainly oxygen and iron. This indicated moisture and general corrosion under insulation on outer shell layer over the time.
- The lack of fusion in the davit pad to outer shell layer fillet weld was observed in visual examination and SEM of the specimen containing the fracture surface. The presence of such a discontinuity at the edge of the weld increases the possibility of crack initiation and propagation over a period of time.
- Visual, macro-examination and scanning electron microscopy of extracted samples showed presence of a pre-existing crack (~3 mm (0.12 in) depth) on the fracture surface, which is clearly differentiated from the fresh rupture face. It appeared to be initiated at the edge of the weld between the pad-plate and shell layer. This was also verified by micro-examination, which clearly showed crack initiation at the edge of the fillet weld and propagation through the outer shell layer.
- The inside surface of the reactor showed signs of corrosion on the liner long seam, circumferential joints, and buttering welds (old cleat removal area). During the air test, weep holes were blocked due to solidifying carbamate in the leak path. The air test performed after the weep holes cleared leakage in the liner long seam. A corrosion attack was observed on the dummy shell layer and 1st shell layer in the vicinity of the liner leakage.
- EDS testing of the deposit collected from the weep hole showed significant nitrogen, oxygen, and carbon presence. This showed carbamate leaked through liner was solidified and deposited at the weep holes. The inside surface of the extracted outer shell layer revealed discoloration towards weep hole-W9 side, which was likely the path of flowing media generated due to weep hole blockages.
- EDS analysis showed a significant amount of oxygen, iron, and other elements like sodium, calcium, magnesium, aluminium, and silicon on the pre-existing crack face and an additional crack beside the fracture surface. The presence of oxygen and iron indicates the formation of iron oxide on the crack face. Other elements appeared to be contributed by the insulation material and water coming from an external source.

Observations from recent repairs in Fertilizer plants

Besides this shell rupture, there have been similar instances of urea reactors leaking through liners and ending up in



long shutdowns from 35-45 days globally [1-6]. Applying innovations, we have designed and developed a special dedicated machine used for *in-situ* rolling of liners inside vessel, which is patented and used for reducing shutdown durations. Typical causes of these failures and remedies to prevent them are summarized below:

- Vent holes are plugged from outside as these are supposed to be removed post-erection. There is no path for the pressure to be released in case pressure is built-up in the shell inter-layers.
- Vent tubes are clogged / blocked, and the leak detection system does not work, increasing the risk of pressure boundary failure by corrosion / rupture in case the liner leaks.
- Random dye penetrant testing of the liner welds, compared to 100% examination, likely results in defects being missed.
- Plant owners concentrate on the liners from the inside and seldom check the pressure boundary from outside. Random non-destructive testing of pressure shell welds should be institutionalized in every shutdown.
- Attachments for liners are welded with partial penetrations. This increases the risk of corrosive medium attacking the crevices and resulting in liner failures.

CONCLUSION

Based on the observations and analysis, the following conclusions can be drawn for the shell rupture:

- Material of the outer shell layer was not degraded. However, thickness of the outer shell layer was reduced by 1.5 mm (0.06 in), possibly due to corrosion under the insulation of the outer shell layer over time.

- Visual examination revealed the presence of a pre-existing crack, initiated near the edge of the fillet weld between the manway davit arm pad plate and the outer shell layer. This could be due to the utilization of the davit arm beyond its design load for various handling activities during earlier shutdowns. Furthermore, discontinuity in the form of lack of fusion increased the possibility of crack initiation and propagation over a period.
- Leakage in liner and blockages of weep tubes during operation resulted in process media entering the shell inter-layers, which in turn exerted pressure on the outer layer. Thickness reduction due to corrosion under insulation and localized reduction in thickness due to pre-existing crack made the outer layer unable to withstand the operating pressure. This led to the bulging of outer shell layer and subsequent shell rupture.

REFERENCES

- [1] Thielsch, H., and F. Cone (1993). Failures, Integrity and Repairs of Petrochemical Plant Reformers. Ammonia Technical Manual, Vol. 33, AIChE, New York.
- [2] Thielsch, H. (1952). Stainless Steel Applied Liners. Welding / Research Supplement, 31,321s.
- [3] Zheng, J. Y., Deng, Y. J., et al. (2005). Experimental investigation on dynamic response and fracture characteristics of discrete multi-layered thick-walled explosion containment vessels. *Explosion and Shock Waves*, 25(6), pp. 506-511.
- [4] Jojima, T. (1979). Urea reactor failure. *Ammonia Plant Safety (and Related Facilities)*, 21, pp. 111-119
- [5] Nicolas, R. W. (1979), *Developments in Pressure Vessel Technology-2 Inspection and Testing*, Applied Science, pp. 25-32.
- [6] Pimshtein, P. G. (1968), *Strength of Multilayer HighPressure Vessels*, *Chemical and Petroleum Engineering (Historical Archive)*, 4(7), pp. 574-578.